

MOLDY CARBINES RECEIVED AT SPRINGFIELD ARMORY, 5 MARCH 1947

Thanks to Billy Pyle for submitting the below photo of a crate of carbines (with #1 bands) with mold issues, as received from an overseas depot. The USA 2-84 and 2-82 designations in the caption refer to "Oil, Rust Preventative, Light...or Heavy." See Newsletter 379 for more information on this subject.



6118-SA SPRINGFIELD ARMORY - ORDNANCE DEPT. 5 March 1947
CARBINE, Cal. .30, M1 as received from overseas for overhaul. Mould
growing thru and over USA 2-84 or 2-82 compound.